




Model 6980FDWAE(MCA)







Item No.	Part No.	No. Used	Description	Item No.	Part No.	No. Used	Description
1	183774-9	1	Housing Set (Includes Item 45)	32	211150-8	1	Ball Bearing 6901ZZ
3	266130-9	8	Tapping Screw Bind PT 3X16	33	213620-3	1	O Ring 46
4	266007-8	1	Tapping Screw Bind PT 3X10	34	911516-9	4	P.H. Screw M4X12
5	416079-5	1	F/R Change Lever	35	317597-5	1	Internal Gear Case
6 .	638326-6	1	Switch Unit	36	638155-7	1	York Unit
7	263024-9	1	Rubber Pin 4	37	619084-3	1	Armature
8	687085-9	1.	Holder	38	638156-5	1	Endbell Com.
9	654168-0	1	Spring Terminal (+)	39	193466-2	2	Carbon Brush CB-434 (2pcs/Set)
10	654169-8	1	Spring Terminal (-)	40	643933-2	2	Brush Holder Cap
11	231951-8	· 1	Ring Spring 11	41	689096-0	1	FET Spacer
12	267085-1	1	Flat Washer 12	42	266170-7	1	Tapping Screw ST3X8
13	233005-7	1	Compression Spring 13	43	266130-9	1	Tapping Screw Bind PT 3X16
14	324420-7	1	Sleeve	44	313118-1	1	Stopper
15	421847-3	1	Bamper	45	819720-3	1	Makita Label
16	153808-2	1	Hammer Case Com.	47	263024-9	1	Rubber Pin 4
17	261108-7	1	Nylon Washer 14				
18	216001-0	2	Steel Ball 3.5				
19	324432-0	1	Anvil M	Access	ories		
20	324262-9	1	Hammer				
21	216001-0	24	Steel Ball 3.5	A01	414938-7	1	Battery Cvover
22	267175-0	1	Flat Washer 24	A02	192598-2	1	12V Ni-Cad Battery 1222 (2.0Ah)
23	233274-0	1	Compression Spring 25				(See Catalogue for other Batteries)
24	267766-7	1	Cup Washer 14	A03	DC1414	1	Charger DC1414 For 7.2V ~
25	216011-7	2	Steel Ball 5.6			-	14.4V, 1.3Ah ~ 3.0Ah
26	226336-1	2	Spur Gear 22				(For Other Chargers, See
27	324220-5	1	Spindle				Catalogue)
28	256253-1	2	Pin 5	A04	183763-4	1	Plastic Carrying Case (Includes
29	267212-0	1	Flat Washer 12			•	Items
30	257254-2	1	Ring 41	A05	417723-7	1	Handle
31	227112-6	1	Internal Gear 51	A06	417724-5	2	Latch

Service Repair Tools

181573-3 - Makita Grease N No.2 1R045 - Large Gear Extractor